




CAST SURFACE

CAST SURFACE

3107

CAST SURFACE

1. REMOVE THE BASE PLATE.
2. DRILL 2 HOLES AND FIX THE BASE TO THE CEILING.
3. MAKE THE ELECTRICAL CONNECTION TO THE TERMINAL BLOCK.
4. INSTALL THE BULB.
5. SCREW THE BODY TO THE BASE PLATE.



DEKKO

12-16 DRAGAN TSANKOV BLVD
1164 SOFIA,
BULGARIA

T +359 (0)2 8168116
F +359 (0)2 8168118

office@dekko.net
www.dekko.net

